

1 East Idaho Street (Feeder's Grain Building)  
1 East Idaho Street  
Paul  
Minidoka County,  
Idaho

HABS No. ID-79

HABS  
ID,  
34-PAUL,  
1-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey  
National Park Service, Western Region  
Department of the Interior  
San Francisco, California 94102

HABS  
ID,  
34-PAUL,  
1-

ARCHITECTURAL DATA FORM

STATE IDAHO	CDUNTY MINIDOKA	TOWN DR VICINITY PAUL
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) 1 East Idaho Street (Commercial Building)		HABS NO. ID-79
SECONDARY OR COMMON NAMES OF STRUCTURE Feeder's Grain Building		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 1 East Idaho Street, Paul, Idaho 83347		
DATE OF CONSTRUCTION (INCLUDE SOURCE) Before 1919 (Pictures & older residents)	ARCHITECT(S) (INCLUDE SOURCE) No information available	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) This building illustrates the historically agricultural economy of the community. It's modest agricultural detail is typical of the early 20th Century structure found in Paul's Commercial Center.		
STYLE (IF APPROPRIATE)		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Unreinforced brick walls with heavy timber and wood frame. Concrete and wood floors, wood frame roof system.		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) See attached sketch plan.		
EXTERIOR FEATURES OF NOTE Corner building with a diagonal corner entrance, featuring a corbelled brick cornice. A sliding door truck entrance is located along East Idaho Street. A corrugated metal addition extends along Main Street. A grain elevator is housed in a frame rooftop structure.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Square timber posts and truss system support the roof, grain elevator and rolling equipment. Grain and feed storage bins are located along the perimeters of the building. Hoppers and grain elevators are located overhead.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES There have been major alterations and additions, but there are no records or information available to know when and exactly what.		
PRESENT CONDITION AND USE Building is deteriorated and has many structural problems. The building is vacant and has not been used for 8 years or more. The structure to be demolished in March 1988.		
OTHER INFORMATION AS APPROPRIATE This building was first occupied as a car garage, later becoming Feeder's Grain. Grain was dumped from trucks to floor pits, then augered along floor augers to elevators that dump grain either into storage bins or overhead hoppers. Some grain was steam-rolled as it was loaded out.		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) City and County records have been checked along with County Historical Society. We also interviewed older residents of the local area. We found there just is not much information available on this building.		
COMPILER, AFFILIATION Richard Rau, Public Works Director for the City of Paul		DATE March 22, 1988

[illegible]

1 East Idaho Street  
HABS No. ID-79  
(page 2)  
Grain & Feed  
Storage

TRUCK  
PIT  
CLAMP

Grain & Feed  
Storage

Grain & Feed  
Storage

Grain &  
Feed  
Storage

Grain & Feed  
Storage

Grain & Feed  
Storage

## Grain & Feed Storage

## Grain & Feed Storage.

Rest  
Room

Electrical  
Panel  
Room

Boiler  
Room

Scale

Truck  
Pit  
Dump

## Wood Beams

Sale &  
Scale  
Office

TRUCK DOOR